




1285P
1285XDIN 844
ISO 1641FRÉZY VÁLCOVÉ ČELNÍ – KRÁTKÉ, HR P, HR, 1 břit přes střed
END MILLS – SHORT, HR P, HR, 1 tooth cut over centre
FRAISE À QUEUE – COURT, HR P, HR, 1 coupe au centre
ФРЕЗЫ КОНЦЕВЫЕ С ЦИЛИНДРИЧЕСКИМ ХВОСТОВИКОМ
– КОРОТКИЕ, HR P, HR, с центрорезущим зубом

www.zps-fn.com



Použití / Usage / Domaines d'application / Употребление

① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬

D k 12	I	L	d h 6	Z	CODE
6	13	57	6	4	128517P.060
8	19	69	10	4	128517P.080
10	22	72	10	4	128517P.100
12	26	83	12	4	128517P.120
14	26	83	12	4	128517P.140
16	32	92	16	4	128517P.160
18	32	92	16	4	128517P.180
20	38	104	20	4	128517P.200
22	38	104	20	5	128517P.220
25	45	121	25	5	128517P.250
28	45	121	25	5	128517P.280
30	45	121	25	5	128517P.300
32	53	133	32	6	128517P.320

D k 12	I	L	d h 6	Z	CODE
9	19	69	10	5	128517X.090
10	22	72	10	5	128517X.100
11	22	79	12	5	128517X.110
12	26	83	12	5	128517X.120
13	26	83	12	5	128517X.130
14	26	83	12	5	128517X.140
15	26	83	12	5	128517X.150
16	32	92	16	5	128517X.160
18	32	92	16	5	128517X.180
20	38	104	20	5	128517X.200

new Z=5Příklad objednávky / Example of order / Exemple de commande / Пример заказа: **128517P.060**1
2
3
4
5
6
7
8